



(1000 10000Gs)

| | mm | mm | mm | Gs | | r/min | T/h | mm | kw |
|------------|------------------|------|-----|-------------|---|--------|-----|----|--------|
| CXJ- 40- | 550× 460× 660 | 400 | 300 | 1000- 10000 | 1 | 17- 82 | 0.6 | 5 | 0.55 |
| CXJ- 60- | 830× 710× 930 | 600 | 400 | | 1 | | 1.5 | 5 | 0.75 |
| CXJ- 60- | 1070× 925× 1240 | 600 | 320 | | 2 | | 2 | 5 | 1.5 |
| CXJ- 60- | 1150× 1070× 1700 | 600 | 406 | | 3 | | 2.5 | 6 | 1.5 |
| CXJ- 80- | 1180× 820× 1040 | 800 | 406 | | 1 | | 2 | 8 | 0.75 |
| CXJ- 80- | 1420× 1220× 1570 | 800 | 406 | | 2 | | 2.5 | 8 | 1.5 |
| CXJ- 80- | 1770× 1260× 1570 | 800 | 406 | | 3 | | 3 | 8 | 2.2 |
| CXJ- 100- | 1300× 1020× 1240 | 1000 | 508 | | 1 | | 2.5 | 10 | 3 |
| CXJ- 100- | 1620× 1420× 1770 | 1000 | 508 | | 2 | | 4 | 10 | 4 |
| CXJ- 100- | 1970× 1460× 2309 | 1000 | 508 | | 3 | | 5.5 | 10 | 5.5 |
| CXJ - 120- | 2006× 1100× 1450 | 1200 | 600 | 1000- 10000 | 1 | 17- 82 | 5 | 10 | 3 |
| CXJ - 120- | 2274× 1700× 2250 | 1200 | 600 | | 2 | | 6 | 10 | 5.5 |
| CXJ - 120- | 2880× 1700× 2950 | 1200 | 600 | | 3 | | 8 | 10 | 3× 3 |
| CXJ - 140- | 2206× 1100× 1450 | 1400 | 608 | | 1 | | 6 | 10 | 4 |
| CXJ - 140- | 2274× 2000× 2250 | 1400 | 608 | | 2 | | 8 | 10 | 7.5 |
| CXJ - 140- | 2800× 2000× 2850 | 1400 | 608 | | 3 | | 10 | 10 | 4× 3 |
| CXJ - 160- | 1960× 1274× 1650 | 1600 | 800 | | 1 | | 10 | 12 | 5.5 |
| CXJ - 160- | 2674× 2160× 2850 | 1600 | 800 | | 2 | | 12 | 12 | 5.5× 2 |
| CXJ - 160- | 3120× 2160× 3700 | 1600 | 800 | | 3 | | 15 | 15 | 5.5× 3 |

()

